

Optivity Telephony Manager, Release 1.1

Optivity Telephony Manager (OTM) 1.1 is now available for all Meridian 1 and Succession CSE 1000 customers. OTM 1.1 builds upon the functionality delivered in OTM 1.01 and provides the following enhancements:

Web Station Configuration Management will allow the administrator or help desk user to change telephone features and keys via the web navigator. End users, if permitted by the administrator, will also be allowed to make changes to features and keys on their own telephone.

Web Alarm Viewer enhancements include the addition of Receive Time, the actual time the alarm was received by the Optivity Telephony Manager server. Device Time data will still be available via the Alarm Details section. Another alarm enhancement is the auto refresh feature, which will allow the administrator to initiate a new alarm retrieval and reset the polling timer. This will provide the administrator with details on any new alarms that have been received by the server.

SNMP Agent Support is provided to integrate Optivity Telephony Manager with HP Openview Network Node Manager (NNM), which will allow alarms collected from Meridian 1 and Succession CSE 1000 devices to be forwarded to NNM.

Succession CSE 1000 Concurrency has been added to Optivity Telephony Manager 1.1 to provide management of Meridian 1 and Succession CSE 1000 through the same interface.

Redundancy Management Support for the Meridian 1 survivable IP expansion cabinet (option 11c release 25.30) will allow certain vital Optivity Telephony Manager operations to function while the expansion cabinet is in survival mode.

Telecom Billing System enhancements include:

- Access to raw CDR data
- Assignments of unique file names and locations for billing reports
- Aux ID and DNIS reports
- SEB II and Pollcat III buffer box support
- Configuration set-up wizard
- Archive, Restore and Purge of the call database



© 2001 Nortel Networks. All rights reserved. Information in this document is subject to change without notice. Nortel Networks Corporation assumes no responsibility for any errors or omissions that may appear in this document.

Nortel, Nortel Networks, the Globemark corporate logo, Meridian, Meridian 1, Optivity and Succession are trademarks of Nortel Networks. All other trademarks are property of their respective owners.